ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W1113, W0836, W1115, W1111, W1117	NA	Hebbal Shanimahatma Temple
Segment No.	**Total Length (m)**	
7/C-W1113/S121353	475.82	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	76.81	77.591735	13.042015	77.591684	13.041323	W0836	Railway Line
2	75.25	77.591634	13.042025	77.591601	13.041346	W0836	Railway Line
3	74.44	77.591569	13.042025	77.591526	13.041354	W0836	Railway Line
4	71.69	77.591406	13.042033	77.591406	13.041385	W0836	Railway Line
5	177.63	77.590228	13.042140	77.591862	13.042025	Shanimahatma Temple	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-4, includes 4 works of Rs 195.00 Lks. 1) Improvements to roads and drains near Hebbal Shanimahatma Temple in Hebbal in Ward No 07, Byatarayana	19500000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Providing and laying CC Road.	007-18-000048, 007-18-000053, 007-18-000054, 007-1
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/159/18-19	31/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
08/02/2019	07/02/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Abhijit.A		0.00

Phone No.	E-Mail ID
9108458111	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
13/02/2019		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W1113, W0836, W1115, W1111,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	15/02/2019	15/03/2019	As proposed
SE	Basavaraj R Kabade	14/02/2019	15/03/2019	forwarded
EE	H.T.Mohandas	13/02/2019	15/03/2019	Verified
AEE	H.Ranganath	13/02/2019	15/03/2019	Verified
AE	Pushpalatha.N.D	13/02/2019	15/03/2019	Mobile verification Done
AE	Pushpalatha.N.D	13/02/2019	15/03/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W1113, W0836, W1115, W1111, W1117

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0202, W0225, W0204	NA	Shabari Nagara
Segment No.	**Total Length (m)**	
7/C-W0202/S012753	367.07	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	161.95	77.589013	13.067074	77.590364	13.066453	Main Road	Dead End
2	205.12	77.588581	13.067012	77.590295	13.066228	Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-4, includes 4 works of Rs 195.00 Lks. 1) Improvements to roads and drains near Hebbal Shanimahatma Temple in Hebbal in Ward No 07, Byatarayana	19500000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Providing and laying CC Road.	007-18-000048, 007-18-000053, 007-18-000054, 007-1
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/159/18-19	31/10/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
08/02/2019	07/02/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Abhijit.A		0.00
Phone No.	**E-Mail ID**	
9108458111		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
13/02/2019		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	15/02/2019	15/03/2019	As proposed

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0202, W0225, W0204

SE	Basavaraj R Kabade	14/02/2019	15/03/2019	forwarded
EE	H.T.Mohandas	13/02/2019	15/03/2019	Verified
AEE	H.Ranganath	13/02/2019	15/03/2019	Verified
AE	Pushpalatha.N.D	13/02/2019	15/03/2019	Mobile verification Done
AE	Pushpalatha.N.D	13/02/2019	15/03/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0202, W0225, W0204

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura

Street ID	Street Name	Significant Landmark
W0278, W0392, W0340, W0266, W0363, W0345, W0339	Lakshmi Sagar Lyt, 1st Crs, 2nd Crs, Mariyappa Lyt, NA, R H B Colcny 1st Main Rd, S Krishnappa Lyt	Amruthahalli Govt School

Segment No.	Total Length (m)
7/C-W0278/S013624	368.58

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	116.40	77.600285	13.065729	77.599808	13.064820	Amruthahalli Main Road	Govt School
2	252.18	77.597640	13.065138	77.599953	13.065159	W0339	W0363

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package-4, includes 4 works of Rs 195.00 Lks. 1) Improvements to roads and drains near Hebbal Shanimahatma Temple in Hebbal in Ward No 07, Byatarayana	19500000	2017-18

Year	Type of Work	Other Work Type
2017 - 2018	Road	

Tender	Work Details	Job No. / Work Code
Tender	1.Providing and laying asphalt Road.	007-18-000048, 007-18-000053, 007-18-000054, 007-1

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/159/18-19	31/10/2018	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
08/02/2019	07/02/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Abhijit.A		0.00

Phone No.	E-Mail ID

9108458111

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalata.N.D
Date of Inspection	**Remarks**	
13/02/2019		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0278, W0392, W0340, W0266,

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	15/02/2019	15/03/2019	As proposed
SE	Basavaraj R Kabade	14/02/2019	15/03/2019	forwarded
EE	H.T.Mohandas	13/02/2019	15/03/2019	Verified
AEE	H.Ranganath	13/02/2019	15/03/2019	Verified
AE	Pushpalatha.N.D	13/02/2019	15/03/2019	Mobile verification Done
AE	Pushpalatha.N.D	13/02/2019	15/03/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0278, W0392, W0340, W0266,